

Ceiling Failure Restoration
Camberwell, London, SE5



Before: Collapsed ceiling



After: Reinstated

Incident:

- Due to excess weight in the loft space above, significant cracks appeared in the bathroom ceiling below.

Outcome:

- ✓ Once it was assessed that there was too much weight on the ceiling above, Abberly Property re-organised the loft and provided strengthening works to the loft floor.
- ✓ A new bathroom ceiling was installed and decorated.
- ✓ The client was provide with a safe and refreshed bathroom environment within 48 hours of initial notification.

Contact Information:

- Freephone 0800 078 6999
- Website www.abberlyproperty.co.uk
- Email help@abberlyproperty.co.uk